

2024 Mazda CX-30

VIN: 3MVDMBBM7RM642158
Inspection Date: November 24, 2025
Prepared By: FastAutoCheck.com

Exterior	2
Glass	3
Tires and Wheels	3
Underbody	3
Underhood	4
Interior	4
Electrical System	5
Road Test Findings	5

Inspection Information

Inspection Date: 2025-11-24	Year: 2024	Make: Mazda
Model: CX-30	Mileage: 36057	VIN: 3MVDMBBM7RM642158
Body Style: SUV	Transmission: Automatic	Engine: 4 cylinder
Drive Type: 4WD	Inspector: Jim Wells	Client Name: Bob Jones
Interior Color: Black	Exterior Color: Black	Door Count: 4

G = Good - This item is in good condition and/or is performing to standard.

F = Fair - This item is in fair condition and/or is performing adequately.

P = Poor - This item is in poor condition and/or is performing below standard.

Exterior

G	F	P	
☒	☐	☐	1. Hood
☒	☐	☐	2. Front
☒	☐	☐	3. Front Bumper
☒	☐	☐	4. Fenders
☒	☐	☐	5. Doors
☒	☐	☐	6. Roof
☒	☐	☐	7. Rear
☒	☐	☐	8. Rear Bumper
☒	☐	☐	9. Trunk
☒	☐	☐	10. Trim
☒	☐	☐	11. Fuel Door
☒	☐	☐	12. Paint Condition

Glass

- | G | F | P | |
|-------------------------------------|-------------------------------------|-------------------------------------|-------------------------------------|
| ☐ | ☐ | ☒ | 13. Windshield - Cracked or chipped |
| ☒ | ☐ | ☐ | 14. Windows |
| ☐ | ☒ | ☐ | 15. Mirrors |
| ☒ | ☐ | ☐ | 16. Rear Window |

Windshield



Tires and Wheels

- | G | F | P | |
|-------------------------------------|-------------------------------------|--------------------------|-------------------------|
| ☐ | ☒ | ☐ | 17. Condition of Tires |
| ☐ | ☒ | ☐ | 18. Condition of Wheels |
| ☒ | ☐ | ☐ | 19. Spare Tire |

Underbody

- | G | F | P | |
|-------------------------------------|--------------------------|--------------------------|--------------------|
| ☒ | ☐ | ☐ | 20. Frame |
| ☒ | ☐ | ☐ | 21. Exhaust System |
| ☒ | ☐ | ☐ | 22. Transmission |
| ☒ | ☐ | ☐ | 23. Drive Axle |
| ☒ | ☐ | ☐ | 24. Suspension |
| ☒ | ☐ | ☐ | 25. Brake System |

Underhood

G	F	P	
☒	☐	☐	26. Engine Compartment
☒	☐	☐	27. Battery
☐	☒	☐	28. Oil
☐	☒	☐	29. Fluids
☒	☐	☐	30. Wiring
☒	☐	☐	31. Belts
☒	☐	☐	32. Hoses
☒	☐	☐	33. Any Non-Stock Modifications

Interior

G	F	P	
☐	☒	☐	34. Seats
☒	☐	☐	35. Headliner
☐	☒	☐	36. Carpet
☒	☐	☐	37. Door Panels
☒	☐	☐	38. Glove Box
☒	☐	☐	39. Vanity Mirrors
☒	☐	☐	40. Interior Trim
☒	☐	☐	41. Dashboard
☒	☐	☐	42. Dashboard Gauges
☒	☐	☐	43. Air Conditioning
☒	☐	☐	44. Heater
☒	☐	☐	45. Defroster

Electrical System



G	F	P	
☒	☐	☐	46. Power Locks
☒	☐	☐	47. Power Seats
☒	☐	☐	48. Power Steering
☒	☐	☐	49. Power Windows
☒	☐	☐	50. Power Mirrors
☒	☐	☐	51. Audio System
☒	☐	☐	52. Onboard Computer
☒	☐	☐	53. Headlights
☒	☐	☐	54. Taillights
☐	☒	☐	55. Signal Lights
☒	☐	☐	56. Brake Lights
☒	☐	☐	57. Parking Lights

Road Test Findings

G	F	P	
☒	☐	☐	58. Starting
☒	☐	☐	59. Idling
☒	☐	☐	60. Engine Performance
☐	☒	☐	61. Acceleration
☒	☐	☐	62. Transmission Shift Quality
☒	☐	☐	63. Steering
☒	☐	☐	64. Braking
☒	☐	☐	65. Suspension Performance

Pictures







Summary

Poor
Glass
Windshield - Cracked or chipped